

## Public Trust Program Inspection Report

| 7  |   |   |  |
|--|---|---|--|
| Inspection Data  | Inspection Time (hrs)   |   |  |
| Body of water: Lake Pend Oreille   | Preparation: 1  | (include instrument type & number)  |  |
| Inspection date: February 27, 2025   | Travel: 1.25  | L96S1673C   |  |
| Type: Quality Assurance  | Inspection: 0.50  |   |  |
| Complaint  | Report: 2   |   |  |
| Application Review, #: L96S1673D   | Total: 4.75   |   |  |
| Name of Instrument Holder/Responsible Party:<br>Juniper Financial Services, LLC  |   |   |  |
| Location of Inspection:<br>90 Kullyspell Drive, Hope, ID 83836<br>RP021700010010A  |   |   |  |
| On-site representative(s):   | 13.7  |   |  |
| Name: Bob Presta   | Name:   | 1.5   |  |
| Title: CE Kramer Crane & Contracting   | Title:  |   |  |
| Phone: 208-264-3021  | Phone:  |   |  |
| Email: Bob.cekramer@gmail.com  | Email:  |   |  |
| Narrative (Describe who, what, when, where, w<br>On February 21, 2025, Tyler Warner, Resource Sp<br>proposed replacing the existing dock and rebuilding  | ecialist- Navigable Waters<br>g the existing boat garage  | The plans included modifications to the   |  |
| dimensions of the boat garage, which had been pre however, the height of the structure had not been depolicy and Procedure, Mr. Warner coordinated with inspection of the site. The purpose of the inspection document the structure's height. They arranged to the morning of February 27, Mr. Warner arrived Navigable Waters, and Meghan Byers, Resource Sonto the property and to the existing boat garage at approximately 9:00 AM, with Mrs. Byers photogray They first measured the master float, followed by the dimensions. Mr. Presta remained present throughout and its distance to neighboring littoral lines. The recorded dimensions for the master float were 28'9", with a height of 10'5".  Summary of Findings: | documented in earlier permith Bob Presta, CE Kramer in was to confirm the exist meet at the property at 9:0 and at the site accompanied pecialist- Navigable Wate and dock, both of which we aphing the site while Mr. Verbe boat garage structure it ut the process, assisting as the er and Mr. Presta discusse in the site was a site of the site while Mr. Verbe was a site of the process. | its. In accordance with Navigable Waterways Crane & Contracting, to schedule an ng dimensions of the boat garage and 0 AM on February 27, 2025.  by Mike Ahmer, Resource Supervisor-rs. Mr. Presta was present to guide the team re on dry land. The inspection began at Varner and Mr. Ahmer took measurements. self, and then recorded the interior needed to ensure accurate data collection.  d the proposed project, including its new |  |
| Summary of Findings:  ☐ No issues of concern identified.  ☐ The following issue(s) of concern were identified.   | ied (include citation and b   | rief description):  |  |
| IDAPA 20.03.04.015.05.b. The proposed plan calls the permitted dimensions of 30' x 35', which would structure dimensions are 21' x 28'9", which would would add 447 square feet to the existing structure  | s for a reconfigured 1,034<br>ld allow a maximum of 1,0<br>I allow for a footprint of 6   | square foot boat garage to be built, based on 050 square feet. However, the current   |  |



## Public Trust Program Inspection Report

**Attachments:** 

Bonner County GIS Aerial photograph 2024

Inspection Map

Photos


| Inspector's Signature: | Name:        | Title/Office:            | Date:     |
|------------------------|--------------|--------------------------|-----------|
| 111)                   | Tyler Warner | Resource Specialist- Nav | 2/27/2025 |
| 19/2/200               |              | Waters                   |           |


L96S1673D

Date: 2/27/2025

Notes: Single Slip

**Not To Scale** 








Figure 1 Bonner County GIS Aerial Image of parcel, 2024




Figure 2 Bonner County GIS Aerial Photo, 2024 showing general vicinity of parcel on East side of Lake Pend Oreille, Hope Peninsula



Figure 3 L96S1673C Boat Garage and Dock



Figure 4- Boat Garage and Dock, looking north



Figure 5- Boat Garage Interior



Figure 6 Boat Garage Interior



Figure 7 Boat Garage Interior from door




Figure 8 Measurements being taken inside boat garage from door



Figure 9 Boat garage from front, looking uphill into interior



Figure 10 Boat garage exterior wall



Figure 11 Boat Garage from upland, note peaked roof



Figure 12- Boat Garage from upland, facing North