
First of the 8 OBJECTIONS, from the Kidd Island Bay Homeowners Association (KIBHA) to the Department of Lands (DOL) regarding the Boat Garage.

1. Many of the Board Members have witnessed the Boat Garage (BG) disintegrate into disrepair over the past 25 years. The owners of the BG did not appear to have an interest in the BG, nor with their fellow members. It is unknown how much of the BG is laying at the bottom of the lake.

The ramp to the BG was partially sinking. It would be difficult to walk the ramp onto the BG. Many of the top boards of the dock are missing. The BG was listing. The BG had lots of holes and a few side panels missing. Lots of patching. On 9-22-2021, when DOL Mrs. Jennifer Barker, inspected the BG, she wrote in her report, "Boat garage was difficult to measure due to it sinking and the master float being in disrepair. Mr. Sharpe stated that the boat garage has its own permit, L95S0446A, and that they would prefer it not to be part of the community dock and would prefer it be relocated." By 3-18-2025, the BG was deconstructed to the flotation logs. See the attached pictures.

OBJ-6A







Dock 15 3'x19.5' ramp, approx. 26'x30' master float, 20'x26' boat garage See L95S0446A

0BJ-6B











Inspection Data	Inspection	on Time (hrs)	Related instrument(s)
Body of water: Coeur d'Alene	Preparatio	n: .25	(include instrument type & number)
Inspection date: 9/22/2021	Travel:	.5	L95S3977
Type: Quality Assurance	Inspection	ı: .25	
☐ Complaint	Report:	.25	
Application Review, #:	Total:	1.25 hr	
Name of Instrument Holder/Responsible Party:			
Kidd Island Bay HOA			
Location of Inspection:			
HOA Parcel that is waterward of AINs 131397 through 110355			
On-site representative(s):			
Name: Don Sharp	Name:		
Title: HOA Dockmaster	Title:		
Phone: 509-949-8028	Phone:		
Email: sharpino@att.net	Email:		
Narrative (Describe who, what, when, where, why, and how):			
Specialist) requested to do a site visit to help clarify the permit and prepare for a new application next season when additional dock(s) would be added to the HOA. Mr. Sharp showed me each dock and we measured the docks that were involved in this permit. Due to a court decision, there are 6 docks that have their own permit, those are 18, 14, 10,9,8, and 3.			
We started measuring in front of AIN 131397 with dock 19 and worked our way up to dock 1 in order of physical location			
Measurements are as follows:			
19 – 4'x8.5' concrete landing, 2'x17' ramp, 8'x25' dock			
18 – individual dock			
17 -3'x18' ramp, 8'x50' dock			
16 – 3.5x2.5 concrete landing, 3'x20' ramp, 6'x40' approach, 8'x50'head (L-shaped dock) 15 – 3'x19.5' ramp, 26'x30' master float, 20'x26' boat garage. Boat garage was difficult to measure due to it sinking and			
the master float being in disrepair. Mr. Sharpe stated that the boat garage has it's own permit, L95S0446A, and that they			
would prefer it not to be part of the community dock and would prefer it be relocated			
14- individual dock			
13 – 3'x29' ramp, 9.5'x40' dock			
12 – 3.5'x17' ramp, 8'x52' dock			
11-3'x7' ramp, 8'x60' dock with boat lift			
10, 9, 8 – individual docks			
7-3'x19' ramp, 8'x50' dock			
6 – 4'x8' pier, 3'x23' ramp, 15'x31' dock. This dock had a bump-out that was greater than 10' in width.			
5 – 4'x8' concrete landing, 4'x19' ramp, 10'x50' dock			
4 – 2'x22' ramp, 7.5'x90' dock			
20 – 2.5'x20' ramp, 8'x71.5'dock 3 -individual dock			
2 – 3'x24' ramp, 8'x28.5' approach, 8'x47' head, (4) 4'x24' fingers creating 3 slips (W)			
$1 - 3^{\circ}$ x32' ramp, 0° x51' dock			

OBJ-bE



10-26-2024 M. MOSS. Tiles

08J-6F




10-26-24 10-26-24 10-26-24 10-26-24

0BJ-6G+

10-27-2024 M. M. M. SS-17118

OBJ-6H



3-17-2025 @ 2:27pm By Baver

085-65

